

17

10


A stack of three boxes made in sheoak by Bill Furber



The Lid scale: full size

ω

60 Ø



A STACK of THREE BOXES

(3 required)

The Boxes

scale: full size

An exercise in precision turning by Ted Stewart-Wynne (WAWA 961)

S31